Serial No. 10/085,357

IN THE SPECIFICATION:

Please replace the paragraph beginning at page 2, line 3 with the following rewritten paragraph:



--Current mail insertion machines include a sensor to detect a low stack condition and a system for alerting an operator to a low stack condition. It is possible in mail processing for an operator to fail to replenish the sheet article stack despite receiving a low stack condition warning. Such a failure to replenish the sheet article supply can result in an unnecessary and undesirable delay in processing. Additionally, in many known insert stations, sheet articles will fall from the sheet article stack onto the track once the sheet article stack size, or level, is less than a certain size.--